



by




DA-F6T/F59T - Twist on connector instruction sheet

To be used with RG6 cable or RG59 airspace cable.

STEP 1 - Strip cable and pull braid over black jacket as in Fig. 1. Leave foil intact ensuring all braid strands are pulled away from centre conductor.

STEP 2 - Place the 'F' connector nut on back to front and twist to ensure that all braid is flat. See Fig. 2.



STEP 3 - Twist body of connector clockwise onto cable till the dielectric of the cable is flush in the bottom of the nut. See Fig. 3.

NB - It is important the centre conductor protrudes 1.5 - 3mm past the nut to ensure good contact with the female connector.

Technical enquiries, call our technical department on 1800 816 460.

